



IF A SHARED LATERAL IS DISCOVERED VIA A PLUMBERS INSPECTION REPORT, OR ANY OTHER ACCREDITED SOURCE, THE FOLLOWING IMPROVEMENTS MUST BE PERFORMED:

- 1) REPAIR OF ALL DEFECTS AS NOTED BY THE INSPECTION REPORT
- 2) ANY LATERAL SEGMENTS THAT NEED TO BE REPLACED WILL ALSO REQUIRE INSTALLATION OF NEW VIEWPORT(S), AS SHOWN ON THE ABOVE SKETCH.

**PROPOSED IMPROVEMENTS
REQUIRED FOR SHARED
SANITARY SEWER LATERAL**

CITY OF LOWER BURRELL